Oil Field Environmental Incident Summary

Responsible Party: Enseco Energy Services **Well Operator:** EOG RESOURCES, INC. **Well Name:** HARDSCRABBLE 23-21H

Field Name: LAKE TRENTON Well File #: 24571

Date Incident: 1/25/2014 Time Incident: 10:30 Facility ID Number:

County: WILLIAMS Twp: 153 Rng: 103 Sec: 21 Qtr: SW SE

Location Description:

Submitted By: Chance Leininger Received By:

Contact Person: Chance Leininger

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	
Oil	2	barrels	2	barrels	2	ı
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/30/2014 Clean Up Concluded: 1/25/2014

Risk Evaluation:

Areal Extent:

Units barrels

Potential Environmental Impacts:

Action Taken or Planned:

Standing oil was revovered with a vac truck. Any remaining oil was removed with absorbant pads. Location surface was ice covered, so there was no affected soil.

Wastes Disposal Location: Recovered fluids were hauled to SWD.

Agencies Involved:

Updates

Date: 1/27/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow (truck or storage), was contained on location. NDIC retains oversight.